

## DRILLING/MILLING AGGREGATES



**code P6314P0015 (ISO 40)**  
2 ways 1/2" Gas coupling + Ø200  
flat disc for straight or lateral cuts



**code P6314P0063 (ISO 40)**  
2 ways 1/2" Gas coupling + Ø200  
flat disc



**code P6314P0016 (ISO 40)**  
2 ways for horizontal milling 1/2"  
Gas coupling (high)



**code P6314P0017 (ISO 40)**  
2 ways for horizontal milling 1/2"  
Gas coupling (low)



**code P6314P0065 (ISO 40)**  
2 ways for horizontal milling 1/2"  
Gas coupling (low)



**code P6314P0064 (ISO 40)**  
2 ways for horizontal milling with  
1/2" Gas coupling (high)



**code P6314P0047 (ISO 40)**  
For low faces boring with 1/2" Gas  
coupling



**code P6314P0040 (ISO 40)**  
For low faces boring with 1/2" Gas  
coupling